



MAINTENANCE NOTES:

- 1) IMMEDIATELY STABILIZE ALL DISTURBED AREAS SURROUNDING PLUNGE POOL ONCE CONSTRUCTED.
- 2) INSPECT RIPRAP WEEKLY AND AFTER SIGNIFICANT RAIN EVENTS TO SEE IF ANY EROSION AROUND OR BELOW THE RIP RAP HAS TAKEN PLACE, OR IF STONES HAVE BEEN DISLODGED. IMMEDIATELY MAKE ALL NEEDED REPAIRS TO PREVENT FURTHER DAMAGE.
- 3) REMOVE SEDIMENT ACCUMULATION FROM RIPRAP IMMEDIATELY AND REFRESH/REPLACE STONE.

PIPE SIZE	A	B	C	D	E	F	G	WT. RIP RAP IN TONS
15"	10'	7'	1 1/2'	1'	1'	4 1/2'	3'	6
18"	12'	8'	2'	1'	1'	5'	4'	8
21"	15'	9'	2 1/2'	1 1/2'	1'	7'	4 1/2'	12
24"	17'	10'	2 1/2'	1 1/2'	1'	8'	5 1/2'	15
30"	20'	13'	3'	2'	2'	9'	6'	22
36"	24'	16'	3 1/2'	2'	2'	9 1/2'	7'	33

IMPORTANT NOTE: DIMENSIONS SHOWN ON CHART ARE FOR REFERENCE AND MAY BE USED IF SUPPORTED BY CALCULATIONS. OTHERWISE USE DIMENSIONS SHOWN ON ACCOMPANYING SHEETS IN PLAN.



STANDARD PLUNGE POOL

DETAIL NUMBER

2024-001
SHEET 1 of 1